



- As the helix angle increases the side load force decreases and the **axial** force increases
- This in turn tries to pull the endmill out of the holder and the part out of the fixturing.